

M40403

Fig. 1

Fig. 2

FOOT-425/6660





Fig. 3





TOOET 464660

Fig. 4

FOOTER: 4262660

Articular Cartilage damage



b1





Fig. 6



0997974-113001

1001




Fig. 7


c



Bone Matrix

Articular Cartilage

2



Bone Matrix

Articular Cartilage


F.S. 8

bl



09997974.113001

b




Bone Matrix






Fig. 9



Articular Cartilage



Articular Cartilage

c

a

b1

b

09997974-113004

FOOETT-42626660





Fig. 10

Fig. 11



0997974-13001